Applicant: Ali-Habib et al.; Serial No. 09/411,496; Atty. Dkt. No. 9D-HL-19210; Title:WASHING MACHINE BRAKE CAM ACTUATOR WITH INTERRUPTED RING; John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis, MO 63102, (314)621-5070

1/4

JUL 26 2002




FIG.1



Applicant: Ali-Habib et al.; Serial No. 09/411,496; Atty. Dkt. No. 2-HL-19210; Title:WASHING MACHINE BRAKE CAM ACTUATOR WITH INTERRUPTED RING; John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis, MO 63102, (314)621-5070

2/4

TECHNOLOGY CENTER 1700




FIG.2




FIG.3



Applicant: Ali-Habib et al.; Serial No. 09/411,496; Atty. Dkt. No. 9D-HL-19210; Title:WASHING MACHINE BRAKE CAM ACTUATOR WITH INTERRUPTED RING; John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis, MO 63102, (314)621-5070




FIG.4




FIG.5



 H_{i-1}^{\perp}

Applicant: Ali-Habib et al.; Serial No. 09/411,496; Atty. Dkt. No. 9D-HL-19210; Title:WASHING MACHINE BRAKE CAM ACTUATOR WITH INTERRUPTED RING; John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis, MO 63102, (314)621-5070

4/4

JUL 26 2002
TECHNOLOGY CENTER 1700




FIG.6